TRUSTED SINCE 1983

359 Tilton Road Northfield, NH 03276 603-934-4145

PO Box 287 Tilton, NH 03276

Buyer

SEPTIC SYSTEM EVALUATION

Prepared For:

Viking Technologies Corporation

Realtor

Homeowner

Other



Date of Inspection:	August 29, 2019	Date Report F	Prepared:	September 2, 2019
Inspection Completed By:	Mike Wing		Kyle Miner	у
Report Prepared By:	Keith Bryant			

603-934-4145

P0 Box 287 Tilton, NH 03276

<u>ContactInformation</u>					
Customer Name:	Viking Techr	nologies Corpoi	ration		
Street Number & Name :	PO Box 219	9			
City: Marblehead		State : MA	Zip : 01945	Phone:	(617) 584-8349
Email Address :	andrey.vegg	ger@gmail.com			
Property Information					
Street Number & Name : 50 Airp	ort Road				ford
Year Built : 1976		Approx	imate Age of Syst	em: Unl	known
Number of Occupants Moving in :			Full Time	Part Tin	ne
Bedrooms : Full Garbage Disposal :	Bath :	3/ Or	4 Bath : Is Not Prese	1/2 Batl ent in the Home	n :
A Water Softener Treatment Syste	em:	ls Or ls Or	Is Not in U	Jse and charging into the	e Septic System
	Lay	out Diagram			
	PUMP CHAMBOTT TANK	Вог	pgan		

603-934-4145

P0 Box 287 Tilton, NH 03276

Inlet Pipe (House to Tank)
Was a Video Camera Analysis Performed : Ves No
Material : V PVC Cast Iron Clay Orangeburg Other :
Condition: Good Fair Poor Repair/Replacement Needed or Recommended? Yes No
Comments :
Viking Enterprise Inlet O2:45:56PM 0.5FT 08/29/2019 00:0035 Page1 (m) 1
Inlet Baffle
Material : PVC Concrete Metal Missing
Condition: Satisfactory Fair Poor N/A
Comments:

Septic Tank

603-934-4145

PO Box 287 Tilton, NH 03276

Location: On the right side of the building, in the lawn area **Fiberglass** Other: Tank Type: Concrete Steel **Plastic** Width: Liquid Height: 4.5 Length: 8 FT Depth: 8 Capacity: 1000 Gallons Inches Below Grade Condition: Poor Fair Next Recommended Pumping Date: As soon as possible Comments: No Photo Available Present (See Below) Pump Chamber: Not present Chamber Capacity: Unknown 200 Gallon Unknown Pump Age: Pump Operation: Insufficient Sufficient **Properly Working** Control Float: Not Working Properly Comments: High level Alarm: No Yes ✓ N/A Operating Properly: Yes No Comments:

603-934-4145

P0 Box 287 Tilton, NH 03276

Outlet Pipe Tank to Ef	fluent Disposal Area (EDA)	
Was a Video Camera Material: P Condition: Good Comments:	VC Cast Iron Clay	Yes No Orangeburg Other: depair/Replacement Needed Recommended: Yes V No
Viking E Outlet	O7PM 2 /FF O0:00:50 Page 1 (p)	Viking Enterprise Outlet
Outlet Baffle		
Material: Condition: Filter present: Comments:	PVC ✓ Concrete Good Fair Yes ✓ No	Metal Missing Poor Missing

603-934-4145

PO Box 287 Tilton, NH 03276

Emuent Disposai Area (EDA):	
Distribution Box: Not Present ✓ Prese	
	Poor Comments: Deteriorated, (wood)
Test Pits dug in the Effluent Disposal Area. Soil	Conditions: Clean and dry
System Type : Stone & Pipe Enviro-Septic Elje	en Concrete Chamber Other:
Location of Leach Field In the lawn area front left of the bu	uilding

603-934-4145

P0 Box 287 Tilton, NH 03276

<u>Summary</u>

Based on the info system is:	rmation gathered at the time of the seption	ic inspection, our rating of the
	is system is in its young or early middle age, luent.	, with no evidence of past flooding
	s system is in middle age, a middle age sys normal working condition of many EDA type	
failing, it m that have	system is nearing the end of its useful life ur nay be in need of replacement, especially lat had little use or have been out of use may h be overcome by repair alone.	ate in its life. Systems in poor condition
	This system meets the statutory definition ator, system failure may be imminent. 485-	
<u> </u>		
Recommer Evaluator	nd Replacing Septic System: Yes 🗸	No Date: August 29, 2019
	,e	
	TO SYSTEM EVALUE	THRE HOLL

603-934-4145

PO Box 287 Tilton, NH 03276

The Service Experts will replace the wooden and deteriorating distribution box with a new concrete distribution box. All connections will be made and any disturbed areas will be re-seeded. Cost \$1145.00 Cost \$1145.00

Cost